



Outline

Review of:

- Bending
- Deep drawing
- Redrawing
- Stretch forming
- Spinning
- Superplastic forming



Example 1: Sheet Bending

A piece of sheet metal has a true strain to fracture of 0.3. What is the minimum bend radius for a piece of this sheet metal if its thickness is 0.5 mm?



Example 2: Deep Drawing

A deep drawing operation is performed on 3.0 mm stock. The part is a cylindrical cup with inside diameter = 70 mm. Find the required starting blank size and whether the operation is feasible or not if,

- (i) The height of the cup is 50 mm and the corner radius on the punch is zero.
- (ii) The height of the cup is 60 mm and the corner radius on the punch is zero.
- (iii) The height of the cup is 60 mm and the corner radius on the punch = 10 mm.



Example 3: Deep Drawing

Is it possible to fabricate a 190 mm diameter cup from an initial blank of 460 mm diameter in three stages, with successive reductions of 40%, 20% and 15%. What is the minimum LDR required for this procedure?



Example 4: Spinning


Estimate the maximum power in shear spinning a 15 mm thick annealed 304 stainless steel ($K = 1275 \text{ MPa}$, $n = 0.45$) that has a diameter of 40 cm on a conical mandrel of $\alpha = 45^\circ$. The mandrel rotates at 100 rpm, and the feed is $f = 25 \text{ mm/rev}$. (**Hint**, the tangential force can be calculated as $F_t = W t_o f \sin \alpha$, $t = t_o \sin \alpha$ and $\epsilon = \frac{\cot \alpha}{\sqrt{3}}$ where W is the specific energy of deformation, t_o is the original thickness)



Example 5: Stretch Forming

A 15 in. long work piece with a cross sectional area of 0.5 in^2 is stretched with a force, F , until $\alpha = 20^\circ$. The material has a true stress-true strain curve $\sigma = 100,000 \varepsilon^{0.3} \text{ psi}$.

- Find the total work done, ignoring end effects or bending.
- What is α_{max} before necking begins?





Example 6: Superplastic Forming and Superplasticity

During a high temperature tensile test of a material, it is noted that changing the strain rate by a factor of 8 increases the true stress by a factor of 3. Is this material superplastic? Support your answer by calculation.



Next topic:
Powder Metallurgy