



POWDER METALLURGY

- Characterization of Engineering Powders
- Production of Metallic Powders
- Conventional Pressing and Sintering
- Alternative Pressing and Sintering Techniques
- Materials and Products for PM
- Design Considerations in Powder Metallurgy




Introduction

- Feasible when
 - (1) the **melting point** of a metal is such as W, Ta, Mo
 - (2) the reaction with the melt becomes a problem. eg. Zr and superhard tool materials
- Powder Metallurgy (PM) (around 1800s)
 - Pressing - Powder compressed into the desired shape.
 - Sintering - Heating at a temperature well below melting.
- Advantage
 - Near-net shape, No waste, Inherent porosity,
 - Dimension control
 - PM production methods can be automated for economical production
- Disadvantage
 -, Powder harder to handle
 - Geometric & Size limitation, Density variation



PM Work Materials

- Largest tonnage of metals are alloys of iron, steel, and aluminum
- Other PM metals include copper, nickel, and refractory metals such as molybdenum and tungsten
- Metallic carbides such as tungsten carbide are often included within the scope of powder metallurgy




A collection of powder metallurgy parts

A *powder* can be defined as a finely divided solid particulates.

- Engineering powders include metals and ceramics
- Geometric features of engineering powders:
 - Particle size and distribution - *Interparticle friction and flow char.*
 - Particle shape and internal structure - *Packing density and porosity*
 - Surface area - *Chemistry and surface film*




Measuring Particle Size



- Most common method uses screens of different mesh sizes
- *Mesh count* - refers to the number of openings per **linear inch** of screen
 - A mesh count of 200 means there are 200 openings per linear inch
 - Since the mesh is square, the count is the same in both directions, and the total number of openings per square inch is $200^2 = 40,000$
 - **Higher** mesh count means



Particles Shapes




Several of the possible (ideal) particle shapes in powder metallurgy



Interparticle Friction and Flow Characteristics

- Friction between particles affects ability of a powder to flow readily and pack tightly
- A common test of interparticle friction is the *angle of repose*, which is the angle formed by a pile of powders as they are poured from a narrow funnel

- Smaller particle sizes generally show greater friction and steeper angles
- Spherical shapes have the interparticle friction
- As shape deviates from spherical, friction between particles tends to increase



Particle Density Measures

- *True density* - density of the true volume of the material
 - The density of the material if the powders were melted into a solid mass
- *Bulk density* - density of the powders in the loose state after pouring
 - Because of pores between particles, *bulk density is less than true density*

Packing Factor = Bulk Density divided by True Density

- Typical values for loose powders range between 0.5 and 0.7
- If powders of various sizes are present, smaller powders will fit into the interstices of larger ones that would otherwise be taken up by air, thus packing factor
- Packing can be increased by **vibrating the powders**, causing them to settle more tightly
- **Pressure applied** during compaction greatly increases packing of powders through rearrangement and deformation of particles



Porosity

- Ratio of the volume of the pores (empty spaces) in the powder to the bulk volume
- **In principle**, Porosity + Packing factor = 1.0
- The issue is complicated by the possible existence of in some of the particles
- If internal pore volumes are included in above porosity, then equation is exact.

Chemistry and Surface Films

- Metallic powders are classified as either
 - *Elemental* - consisting of a pure metal
 - *Pre-alloyed* - each particle is an alloy
- Possible surface films include oxides, silica, adsorbed organic materials, and moisture
 - As a general rule, these films **must be removed** prior to shape processing





Production of Metallic Powders


1. Atomization
- Centrifugal, gas or water
2. Chemical
- Decomposition or precipitation
3. Electrolytic

Mechanical methods are occasionally used to reduce powder sizes

e.g. iron powders produced by decomposition of iron pentacarbonyl; particle sizes range from about 0.25 - 3.0 microns




Conventional Pressing and Sintering



- After the metallic powders have been produced, the conventional PM sequence consists of three steps:
 1. **Blending** and **mixing** of the powders
 2. **Compaction** - pressing into desired part shape
 3. **Sintering** - heating to a temperature below the melting point to cause solid-state bonding of particles and strengthening of part
- In addition, secondary operations are sometimes performed to improve **dimensional accuracy**,, and for other reasons.



Sintering




- Heat treatment to bond the metallic particles, thereby increasing strength and hardness
- Usually carried out at between 70% and 90% of the metal's melting point
- Generally agreed among researchers that the primary driving force for sintering is
- **Part shrinkage** occurs during sintering due to pore size reduction



Sintering

Typical heat treatment cycle in sintering

schematic cross-section of a continuous sintering furnace



- Secondary operations** are performed to increase density, improve accuracy, or accomplish additional shaping of the sintered part
- **Repressing** - pressing the sintered part in a closed die to increase density and improve properties
 - **Sizing** - pressing a sintered part to improve dimensional accuracy
 - **Coining** - pressworking operation on a sintered part to press details into its surface
 - **Machining** - creates geometric features that cannot be achieved by pressing, such as threads, side holes, and other details



Impregnation and Infiltration

- Porosity is a unique and inherent characteristic of PM technology
- It can be exploited to create special products by filling the **available pore space with oils, polymers, or metals**
- **Impregnation:** The term used when oil or other fluid is permeated into the pores of a sintered PM part
 - Common products are oil-impregnated bearings, gears, and similar components
 - An alternative application is when parts are impregnated with polymer resins that seep into the pore spaces in liquid form and then solidify to create a **pressure tight part**
- **Infiltration:** An operation in which the pores of the PM part are filled with a **molten metal**
 - The melting point of the filler metal must be **lower**
 - Involves heating the filler metal in contact with the sintered component so capillary action draws the filler into the pores
 - The resulting structure is relatively **nonporous**, and the infiltrated part has a more **uniform density**, as well as **..... toughness and strength**

Dr. M. Medraj


Mech. Eng. Dept. - Concordia University

Mech 421/6511 lecture 12/13



Alternative Pressing and Sintering Techniques

- The conventional press and sinter sequence is the most widely used shaping technology in powder metallurgy
- Isostatic Pressing
 - Cold Isostatic Pressing (CIP)
 - Hot Isostatic Pressing (HIP)
- Powder Injection Molding (Metal & Ceramics)
 - Powder mixed with binder to form granular pellets
 - Pellets are heated to remove binder
 - Sintering and Secondary operation
- Powder Rolling, Powder Extrusion (powder in a container) and Powder Forging
- Hot pressing and Spark pressing (high electric current)
- Liquid-phase sintering




Dr. M. Medraj

Mech. Eng. Dept. - Concordia University

Mech 421/6511 lecture 12/14



Liquid Phase Sintering of AlN



Dr. M. Medraj


Mech. Eng. Dept. - Concordia University

Mech 421/6511 lecture 12/15




Liquid Phase Sintering of AlN

With yttria




Without yttria



1µm

AlN-Al₂O₃-Y₂O₃
Isothermal Section at
1800°C



Note that liquid forms at a lower temp. than the T_m of any of the components

Dr. M. Medraj

Mech. Eng. Dept. - Concordia University

Mech 421/6511 lecture 12/16





Materials and Products for PM

- Raw materials for PM are than for other metalworking because of the additional energy required to reduce the metal to powder form
- Accordingly, PM is competitive only in a certain range of applications
- What are the materials and products that seem most suited to PM?
- Common elemental powders:
 - Iron, Aluminum and Copper
- Used in applications where high purity is important
- Elemental powders are also mixed with other metal powders to produce special alloys that are difficult to formulate by conventional methods
 - Example: tool steels
- Pre-Alloyed Powders: Each particle is an alloy comprised of the desired chemical composition
- Used for alloys that **cannot** be formulated by mixing elemental powders
- Common pre-alloyed powders:
 - Stainless steels, Certain copper alloys and High speed steel



PM Products



- Gears, bearings, sprockets, fasteners, electrical contacts, cutting tools, and various machinery parts
- Advantage of PM: parts can be made to or
- They require little or no additional shaping after PM processing
- When produced in large quantities, gears and bearings are ideal for PM because:
 - The geometry is defined in two dimensions
 - There is a need for porosity in the part to serve as a reservoir for lubricant





Design Guidelines for PM Parts

- Economics usually require large quantities to justify cost of equipment and special tooling
 - Minimum quantities of units are suggested
- PM is unique in its capability to fabricate parts with a **controlled level of porosity**
 - Porosities up to are possible (e.g. Metal foams)
- PM can be used to make parts out of **unusual metals and alloys** - materials that would be difficult if not impossible to produce by other means
- The part geometry must permit **ejection** from die after pressing
 - This generally means that part must have vertical or near-vertical sides, although steps are allowed
 - Design features such as **undercuts and holes** on the part sides must be avoided
 - Vertical undercuts and holes are permissible because they do not interfere with ejection
 - Vertical holes can be of cross-sectional shapes other than round without significant difficulty




Design Guidelines for PM Parts

- Screw threads cannot be fabricated by PM; if required, they must be machined into the part
- Chamfers and corner radii are possible by PM pressing, but problems arise in **punch rigidity** when angles are too acute






Metal Foams Produced by PM



Production Steps of IMI metal foam

This process can produce a very porous structure



Microstructure of the metal foam produced at IMI-NRC



*Next time
Processing of Ceramics*