



Outline:

- Example 1: *Tool geometry*
- Example 2: *Cutting forces and Power*
- Example 3: *Time Analysis for Milling*
- Example 4: *Tool Life*
- Example 5: *Cutting Temperature*
- Example 6: *Orthogonal cutting*
- Example 7: *Drilling*



Example 1: Tool Geometry

What roles do rake and relief angles play in cutting tools?



Example 1: Cutting forces and Power

In orthogonal machining the tool has rake angle 10° , chip thickness before cut is $t_o = 0.02$ in, and chip thickness after cut is $t_c = 0.045$ in. The cutting and thrust forces are measured to be $F_c = 350$ lb and $F_t = 285$ lb while at a cutting speed of 200 ft/min. Determine the machining shear strain, shear stress, and cutting horsepower.




Example 2: Time Analysis for Milling

A face milling operation is performed to finish the top surface of a steel rectangular workpiece 12 in. long by 2 in. wide. The milling cutter has 4 teeth (cemented carbide inserts) and is 3 in. in diameter. Cutting conditions are 500 rpm, $f = 0.01$ in./tooth, and $d = 0.150$ in. Determine the time to make one pass across the surface and the metal removal rate during the cut.

Solution:

Allow for over-travel O where $A = O$:

Full face $A = O = D/2$





Example 3: Tool Life

The n and C values in accompanied table are based on a feed rate of 0.01 in./rev and a depth of cut of 0.10 in. Determine and compare the cubic inches of steel removed for each of the following tool materials if a 15 minute tool life is required in each case: a) HSS b) ceramic

Solution:

| Tool Material | n | V /min | C (m/min) |
|--------------------------------|-------|----------|----------------|
| Plain carbon tool steel | | | |
| Nonsteel cutting | 0.1 | 200 | (70) |
| Steel cutting | 0.1 | 60 | (20) |
| High-speed steel | | | |
| Nonsteel cutting | 0.125 | 350 | (120) |
| Steel cutting | 0.125 | 200 | (70) |
| Cemented carbide | | | |
| Nonsteel cutting | 0.25 | 2700 | (900) |
| Steel cutting | 0.25 | 1500 | (500) |
| Cermet | | | |
| Steel cutting | 0.25 | 2000 | (600) |
| Coated carbide | | | |
| Steel cutting | 0.25 | 2200 | (700) |
| Ceramic | | | |
| Steel cutting | 0.6 | 10000 | (3000) |

For turning at feed = 0.01"/rev. and depth = 0.100 "



Example 4: Cutting Temperature

Consider a turning operation performed on steel whose hardness = 225 HB at a speed = 3.0 m/s, feed = 0.25 mm, and depth = 4.0 mm. Compute an estimate of cutting temperature using the Cook's equation. Assume ambient temperature = 20°C.

Solution:

$$\Delta T = \frac{0.4U}{\rho_c} \left(\frac{vt_o}{K} \right)^{0.333}$$



Example 5: Orthogonal Cutting

Assume that in orthogonal cutting, the rake angle is 15° and the coefficient of friction is 0.25 determine the percentage change in chip thickness when the friction is doubled.



Example 6: Drilling

A hole is being drilled in a block of magnesium alloy with a 10 mm drill at a feed of 0.1 mm/rev. The spindle is running at 800 rpm. Calculate the material removal rate, and estimate the torque on the drill (*Hint: The unit power for Mg-alloys is about 0.5 W.s/mm³*).



Next Lecture:
Friction and Lubrication